

FIG. 1





FIG. 2



002221" 5T42460

FIG. 3




FIG. 4




FIG. 5




FIG. 6


PHOTOGRAPH 1



MICROPHOTOGRAPH ($\times 100$)

FIG. 7


PHOTOGRAPH 2



MICROPHOTOGRAPH ($\times 100$)


FIG. 8

PHOTOGRAPH 3




FIB PHOTOGRAPH OF CORROSION PART

FIG. 9
PHOTOGRAPH 4



FIB PHOTOGRAPH OF FILM LIFTING PHENOMENON


FIG. 10
PHOTOGRAPH 5



SAMPLE ×200

FIG. 11

PHOTOGRAPH 6



UNUSUAL PART ×500

FIG. 12

PHOTOGRAPH 7



UNUSUAL PART ×1000

09/4/24 15:42:20

FIG. 13

SEM PHOTOGRAPH OF Cr FILM SURFACE ×100K




FIG. 14

SEM PHOTOGRAPH OF TiO₂ FILM SURFACE ×100K

